

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definiti on
1	BRS	L1	54	455/232.1.ccls. and AGC	USPAT	2004/02/20 16:08		
2	BRS	L2	0	455/232.1.ccls. and AGC with DPSK	USPAT	2004/02/20 16:03		
3	BRS	L3	0	455/232.1.ccls. and AGC same DPSK	USPAT	2004/02/20 16:03		
4	BRS	L5	5	AGC with DPSK	USPAT	2004/02/20 16:07		
5	BRS	L6	19	AGC same DPSK and 455/\$.ccls.	USPAT	2004/02/20 16:05		
6	BRS	L7	52	AGC same DPSK	USPAT	2004/02/20 19:09		
7	BRS	L9	1	455/234.1.ccls. and AGC same quadrature adj (downconvert\$3 or down-convert\$3 or down adj convert\$3)	USPAT	2004/02/20 16:09		
8	BRS	L8	190	455/234.1.ccls. and AGC	USPAT	2004/02/20 16:12		
9	BRS	L4	52	AGC same DPSK	USPAT	2004/02/20 16:17		
10	BRS	L10	1	6324387.pn.	USPAT	2004/02/20 16:17		
11	BRS	L11	28	coaxial adj RF adj cable	USPAT	2004/02/20 19:17		
12	BRS	L12	4	455/\$.ccls. and 11	USPAT	2004/02/20 19:11		
13	BRS	L13	6	("5293175" "5523768" "5719586" "5754145" "6014112" "6037911").PN.	USPAT	2004/02/20 19:16		
14	BRS	L14	0	coaxial adj RF adj cable and 13	USPAT	2004/02/20 19:16		
15	BRS	L15	6	coaxial adj RF adj cable and dipole	USPAT	2004/02/20 21:14		
16	BRS	L16	22	11 not 15	USPAT	2004/02/20 22:24		